

Xplor 600Pro II Firmware Instruction

- 1. Please update the firmware with Flashpoint firmware update software F3 Windows V1.1 or F3 MacOS V1.1. Both can be downloaded from the official website.
- 2. How to check the version number: Turn on the gear, and enter the menu settings to check the version number in Device Info. (e.g., Version 1.1: V1.1).
- 3. Version Description:

Version	What's New	Date
V1.08	1. Added FT433's compatibility with FT-16	2025-03-03
V1.07	1. Added 433 MHz triggering functionality 2. Fixed an issue where the fan remained on after connecting the head extension cable	2024-10-21
V1.06	Optimized the TTL function	2024-08-22
V1.05	Optimized the TTL function	2024-08-14
V1.0	Initial Version	V1.0

Note: For more details, please download the latest instruction manual from the official website