

Magnetic Wall-Mounted Glass Board Instructions

WGB4836M | WGB6040M | WGB7248M | WGB9648M

Tools Required:

Phillips Head Screwdriver



- Use a 1/4" drill bit to create pilot holes for the included anchors.
- Use a 1/8" drill bit to create pilot holes for screwing directly into studs.

Parts List - WGB4836M & WGB6040M:

Parts List - WGB7248M & WGB9648M:



A x 6



B x 6



C x 2



D x 2



E x 2















D x 3

Drill





E x 3

F x 1







